

C.L. "BUTCH" OTTER - Governor RICHARD M, ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

May 24, 2007

Dee Cullum, Administrator Renaissance Assisted Living - Mountain View PO Box 1687 Idaho Falls, ID 83403

License #: RC-840

Dear Ms. Cullum:

On April 24, 2007, a life safety code survey was conducted at Renaissance Assisted Living - Mountain View. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

May 11, 2007

Dee Cullum, Administrator Renaissance Assisted Living - Mountain View PO Box 1687 Idaho Falls, ID 83403

Dear Ms. Cullum:

On April 24, 2007, a life safety code survey was conducted at Renaissance Assisted Living - Mountain View. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by May 24, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

ph for

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau o	of Facility Standards	i						
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01 - BUILDING 1  B. WING		(X3) DATE SURVEY COMPLETED 04/24/2007		
NAME OF P	ROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, ST	ATE, ZIP CODE	0-1/2	17200.	
	SANCE ASSISTED LI	VING - MOUNTAIN	130 VALL	LEY CENTER DRIVE ID 83422				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTI CROSS-REFERENCED TO TI DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETE DATE	
R 000	compliance with the requirements of the Assisted Living Factoricies were of fire/life safety survey 2007.		al or ore lard il 24,	R 000				

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



## BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

SARA SEL

Facility Name			Physical Address	Phone Number								
•		A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•									
1CONAIS	SANDE	Assisted Living -MTN View	130 Valley Center DR.	(208) 354 ZIP Code	1-0261							
Dee (	<u>London</u>	~	DRIGGS Id	83422	-							
TAYLOR BANKLEY			Survey Type	Survey Date								
				4.24-	1							
NON-CORE ISSUES												
	RULE # 16.03.22		DESCRIPTION DESCRIPTION		DATE RESOLVED	BFS USE						
1 40	15.05	The furnace room has four	inch by six inch hole in the ceil	NG.								
	5.01	Resident Room 10 15	Missing two electrical outlet cou	iers.								
3. 410	0.03	The facility did Not con		1512570								
		Der QUARTER AS require										
4, 41.	5.02	l 1. ^										
		clevice Inspection from a person professionally engaged in										
	device Inspection from a person professionally engaged in the business of servicing these devices.											
5, 415	5.01	The sprinkler head in the closet of resident room #11 still										
		has the manufactors cover plate installed.										
						2000						
	***************************************											
						31313						
Response Required Date Signs		Signature of Facility Representative			Date Signed 7							
5.24-7		Dle Ceelleen										